

SANDHU & ASSOCIATES

Dr. R.S. Sandhu

20/10/2012, 10:00 AM

- Structural Engineering
- Estimation & Costing
- Quantity Surveying
- Project Management
- Site Inspection
- Surveying
- Drawing
- Inspection



Ref. No. Z3/21 / SA/11/22

Dated: 25/11/2022

SAFETY CERTIFICATE

Name of Building: MAHARISHI INTERNATIONAL PUBLIC SCHOOL
 Location: NEAR NEW GRAIN MARKET, BEHIND VEER RICE MILL,
 GHARAUNDA, DISTT.-KARNAL, HARYANA 132114.

TECHNICAL/ GENERAL DETAILS OF THE BUILDING/ STRUCTURE

- | | |
|---|--------------------------------------|
| 1. Description of building
(Residential/Commercial/Industrial) | School Building |
| 2. Description of boundaries: | |
| North: | Neighbouring land of Bajaj Rice Mill |
| South: | Land of Sh. Sohan Lal |
| East: | Neighbouring land of Bajaj Rice Mill |
| West: | Gharaunda- Hassanpur Road |
| 3. Type of construction
(Load bearing/R.C.C./Steel framed) | R.C.C. Framed Structure |
| 4. Year of Construction. | 2006-07 |
| 5. Number of floors & height of each floor including basement, if any | Ground Floor + 3 Floor |
| 6. Condition of the building | Good |
| 7. i) Exterior-Excellent Good,
Normal, Poor | Normal |
| 8. ii) Interior-Excellent Good
Normal, Poor | Normal |

PRINCIPAL
 Maharishi International Public School
 Gharaunda (Karnal)





sandhu & associates
 Civil & Structural Engineer
 20/10/2012, 10:00 AM

SPECIFICATION OF CONSTRUCTION (FLOORWISE) IN RESPECT OF

Sr.No.	Description	Ground Floor	First Floor
01	Foundation	Stepped footing foundation	N.A.
02	Superstructure	Brick masonry in cement sand mortar	Same as ground floor
03	Joinery/Doors & Window (Please furnish details about size of frame shutters, glazing, fitting etc. and specify the species of timber)	Wooden doors and windows	Same as ground floor
04	R.C.C. Works	RCC slab roofing	Same as ground floor
05	Plastering	Cement plastering pointing on walls	Same as ground floor
06	Flooring, Skirting, Dadoing	Marble flooring, Terrazo Flooring	Same as ground floor
07	Special finish as Marble, Granite, Wooden paneling, Grilles etc.	Nil.	Nil
08	Roofing including weather proof course	RCC slab roofing	Same as ground floor
09	Drainage	Satisfactory	Satisfactory

It is certified that this RCC framed structure/ Building seems to be safe under normal conditions after visiting and inspecting the site by the undersigned on dt. 25.11.2022.

 **sandhu & associates**
Civil & Structural Engineer
91-F, Naya Bazar Market
Near Clock Tower, Karnal (Haryana)


PRINCIPAL
Maharishi International Public School
Gharaunda (Karnal)