



Ref. No.....S28

Dated...30/03/26

BUILDING SAFETY & SOUND CERTIFICATE

I have personally visited & inspected the site existing School Building situated at **NEAR NEW GRAIN MARKET, BEHIND VEER RICE MILL, GHARAUNDA, DISTT. KARNAL HARYANA**. In the name of "**MAHARISHI INTERNATIONAL PUBLIC SCHOOL**"

Examine the plan & specification of building described below:

Height of Roof, Actuals material used in its construction & the finished building & satisfied.

Work Specification of Building :- Brick masonry work in cement mortar in foundation & super Structure, 9" Thick, Bricks wall, R.C.C. Slab Roofing, Cement Cone, Flooring, Elec. Fitting, wooden doors & window, Cement plaster both side of wall, water & sewerage fitting & white washing & painting work.

This building structurally sound & good maintained condition at this time.

As per my observation and opinion the building is supposed to be safe stable if periodically repaired and maintained where as it does not involve the unnatural happening hence certified.

Dated: 30-03-2026

